

Work Perm	it #	
Work Order	r#	
Job#	Activity#	

Work requester fills out this section.	☐ Standi	ng Work Permit		, <u> </u>
Requester: Don Lynch	Date: 1/11/2006	Ext.: 2253	Dept/Div/Group: PO)/PHENIX
Other Contact person (if different from	requester): Sal Marino		Ext.: 3704	
Work Control Coordinator: Don Lynch	1	Start Date: 1/12/2006	Est. End Date: 2/28/	/2006
Brief Description of Work: Install MPC	South Detector in MMS piston cav	ity		
Building: 1008	Room: IR	Equipment: MPC	Service Provider: Ph	HENIX
WCC, Requester/Designee, Service Pro	ovider, and ES&H (as necessary)	fill out this section or attach an	alysis	
ES&H ANALYSIS				
	None	Airborne	☐ Contamination	Radiation
	Radiography	☐Moisture Density Gauges	Soil Density Gauges	
☐ Special nuclear materials involve	ed, notify Isotope Special Materials	Group	☐ Fissionable materials in	nvolved, notify Laboratory Criticality Officer
Safety Concerns	☐ None	☐ Ergonomics	☐ Transport of Haz/Rad N	Material
☐ Adding/Removing Walls or Roof	Confined Space*	☐ Explosives	☐ Lead*	☐ Penetrating Fire Walls
Adding/ternoving vvalis of feet	☐ Corrosive	☐ Flammable	☐ Magnetic Field*	☐ Pressurized Systems
☐ Asbestos*	☐ Cryogenic	☐ Fumes/Mist/Dust*		☐ Rigging/Critical Lift
☐ Beryllium*	☐ Electrical	☐ Heat/Cold Stress	☐ Noise*	☐ Toxic Materials*
☐ Biohazard*		☐ Hydraulic	☐ Non-ionizing Radiation*	*
☐ Chemicals*	☐ Excavation	☐ Lasers*	☐ Oxygen Deficiency*	Other: Working near beampipe
* Does this work require medical clear	arance or surveillance from the Occ	upational Medicine Clinic? Ye		
Environmental Concerns		None Non	☐ Work impacts Environm	nental Permit No.
☐ Atmospheric Discharges (rad/no	on-rad)	☐ Land Use	Soil	☐ Waste-Mixed
☐ Chemical or Rad Material Storage	<u> </u>	Liquid Discharges	Activation/contamination Waste-Clean	☐ Waste-Radioactive
	90 01 000	Oil/PCB		
Cesspools (UIC)		Management	☐ Waste-Hazardous	☐ Waste-Regulated Medical
☐ High water/power consumption		☐ Spill potential	☐ Waste-Industrial	☐ Underground Duct/Piping
Waste disposition by:				☐ Other
Pollution Prevention (P2)/Waste M		None ☐ Yes		
FACILITY CONCERNS	None Non			
☐ Access/Egress Limitations	Electrical Noise	☐ Potential to Cause a		Vibrations
_	☐ Impacts Facility Use A		☐ Temperature Change	☐ Other
Configuration Control	☐ Maintenance Work on	Ventilation Systems	Utility Interruptions	
WORK CONTROLS				
Work Practices				
None	Exhaust Ventilation	Lockout/Tagout Posting/Warning	Spill Containment	Security (see Instruction Sheet)
☐ Back-up Person/Watch	☐ HP Coverage	Signs	☐ Time Limitation	☐ Other
Barricades	☐ IH Survey	☐ Scaffolding-requires	☐ Warning Alarm (i.e. "hig	nh level")
		inspection		grillovoi)
Protective Equipment				
None	☐ Ear Plugs	Gloves	☐ Lab Coat	Safety Glasses
☐ Coveralls	☐ Ear Muffs	☐ Goggles	☐ Respirator	☐ Safety Harness
☐ Disposable Clothing	☐ Face Shield		☐ Shoe Covers	Safety Other
Permits Required (Permits must be	valid when job is scheduled.)			3.1000
None Non	☐ Cutting/Welding	☐ Impair Fire Protection	n Systems	
☐ Concrete/Masonry Penetration	☐ Digging/Core Drilling	Rad Work Permit-RW	-	
☐ Confined Space Entry	☐ Electrical Working Ho			
Dosimetry/Monitoring				
None Non	☐ Heat Stress Monitor	Real Time Monitor	☐ TLD	
☐ Air Effluent	☐ Noise Survey/Dosime	ter Self-reading Pencil Dosimeter	☐ Waste Characterization	1
Ground Water	O ₂ /Combustible Gas	Calf as adia a Distra	☐ Other	
☐ Liquid Effluent	☐ Passive Vapor Monito	Sorbent Tube/Filter		
Training Requirements (List below	specific training requirements)			
Based on analysis above, the Wal	kdown Team determines the risk.	complexity, and coordination		all hazard ratings are low, only the following
ratings below:	Tony	, , , , , , , , , , , , , , , , , , , ,	need to sign: (Although a form)	allowed, there is no need to use back of
ES&H Risk Level:	Low Modera	ate High	WCC:	Date:
Complexity Level:	☐ Low ☐ Modera	<u>_</u>	Service Provider:	Date:
Work Coordination:	Low Modera		Authorization to start	Date:
		— ' "у"	(Description to start	

	Work Plan (procedures, timing, eq See attached procedure	uipment, and personne	l availability nee	d to be addressed)				
-	Special Working Conditions Require None	ed:						
-	Operational Limits Imposed: None							
-	Post Work Testing Required: No							
-	Job Safety Analysis Required:	Yes 🛛 No			Walkdown Reg	uired: X Yes	□ No	
-	, , , , _	_			<u>'</u>			
	Reviewed by: Primary Reviewer we that the hazards and risks that could	rill determine the size o	f the review tear een identified an	n and the other sigr d will be controlled	natures required to according to BNL	pased on hazard requirements.	ls and job complexi	ty. Primary Reviewer signature means
	<u>Title</u>	Name (print)		<u>Signature</u>		Life #		<u>Date</u>
	Primary Reviewer							
	ES&H Professional							
	Other							
	Other							
	Work Control Coordinator	Don Lynch						
	Service Provider							
		Review Done:	in series	☐ team				
		l .				1		
. Job	site personnel fill out this section Note: Signature indicates personne		rood and undo	ratand the hazarda	and parmit require	omanta (inaludin	a any attachmente	
		i periorning work have	reau anu unuei	Statiu tile Hazarus i		•	g any attachments,	
_	Job Supervisor:	Life#:			Contractor Sup Workers :	ervisor:	Life#:	
-	Workers:	Lile#.			Workers .		LIIE#.	
_								
_								
_			.,					
L	Workers are encouraged to provide	feedback on ES&H co	ncerns or on ide	as for improved job	work flow. Use f	eedback form oi	space below.	
. De <u>p</u>	artmental Job Supervisor, Work C	ontrol Coordinator/D	esignee					
	Conditions are appropriate to start v	vork: (Permit has beer	reviewed, work	controls are in place	e and site is read	ly for job.)		
	Name:	Signati	ıre:		Life#:		Date:	
Den	artmental Job Supervisor, Work R	eauester/Desianee d	etermines if Po	st .loh Review is re	anuired Yes	s III No		
. 502	Post Job Review (Fill in names of re		, , , , , , , , , , , , , , , , , , ,		<u> </u>	<u> </u>		
-	Name:	Signati	ıre:		Life#:		Date:	
-	Name:	Signati	ıre:		Life#:		Date:	
L								
. Wor	ker provides feedback. Worker Feedback (use attached she	eets as necessary)						
	a) WCM/WCC: Is any feedback re		No					
	b) Workers: Are there better method	ods or safer ways to pe	rform this job in	the future? Ye	s 🗌 No			
	eout: Work Control Coordinator (ecks quality of o	completed permit	and ensures the	work site is lef	t in an acceptable	condition. (WCC can delegate
	Name:	Signati	ıre:		Life#:		Date:	
-	Comments:						I	

Work plan A	Attachment
-------------	------------

WP#

MPC South Detectors PHENIX IR, Bldg. 1008

Discussion

A new array of detectors has been designed and built for the PHENIX experiment at the Relativistic Heavy Ion Collider. The design concept for the detectors has been reviewed by appropriate PHENIX technical staff and a safety review by CA safety staff has been conducted during which the concept for this work plan was presented.

The detector is comprised by 8 separate enclosures of 2 generic configurations housing a total of 188 lead tungstate crystals 29 of which are housed in each of 4 wedge shaped corner modules and 18 crystals in each of 4 brick shaped central module. The enclosures provide a light tight environment for the detectors which have dry air supplied in an open loop to maintain a uniform thermal environment. On the exterior of the enclosures in the side facing the IP printed circuit boards are attached, from which signal cables and HV/LV power cables are routed from the front end electronics. LED's are mounted on the opposite face (facing away from IP). The front end electronics are mounted above the center MuTr electronics rack on the "eyebrow".

The detector enclosures will be installed 1 at a time by hand with support from the overhead crane to help support the weight when positioning the module for insertion. The attached diagrams show the order and orientation in which the detector modules are to be inserted.

This work is to be done by fully trained and experienced PHENIX personnel, under the technical supervision of Sal Marino and the engineering cognizance of Don Lynch. The modules will be inserted using an articulated manlift with 2 PHENIX mechanical technicians in the lift to support and insert each module and an additional technician on the ground to operate the crane for load support. The actual mechanical work requires mechanical technician skill of the craft to insert the individual modules, integrate them into a single detector system, align the system to its ultimate position and anchor the assembly at that position.

All persons involved will have appropriate training for working at heights, fall protection and all other relevant training.

Procedure

LOTO the power to the MMS magnet coil at the power supply in1008B. (Pearson)


Assure that the CM is locked in position by locking out the hydraulics to each magnet mover. (Marino)

Insert each of the modules individually into the piston cavity using the installation tool shown on the attached sheets and in accordance with the sequence and orientation graphically illustrated on the attached sheets. Maintain extreme care at all times to prevent contact with the beam pipe.

After installing, integrating, positioning and aligning the assembly make sure that all tools and any other foreign matter are removed from the piston hole.

Attach signal and power cables as required and route them into the provided cable tray to the MPC electronics crate.

At this point the MMS magnet may be released from its hydraulics lockout to be moved north to its run position and the detector commissioning may commence.




8 modules:


- 4 wedges w/ 29 crystals each
- 4 bricks w/18 crystals each
- 188 crystals total




Modules are attached to adjacent modules with tab/slots at rear and screws at front















1. Insert lowerwest wedge module



2. Rotate lowerwest wedge module counter-clockwise, insert lower-east module

3. Rotate lower wedge modules to normal position




4. Rotate lower wedge modules clockwise, insert below-center west block module



5. Rotate modules back to normal position. Insert below-center east block module

7. Rotate modules to normal position. Insert babove-center West block module




6. Rotate modules counter-clockwise, insert above-center east block module

8. Ready for upper wedge modules




9. Rotate modules counter-clockwise. Insert upper east wedge



10. Rotate modules clockwise, to normal position. Insert upperwest wedge module

11. Connect cables and gas lines, push assembly to back wall of cavity align and lock in position





MPC after all modules are installed, before moving back in cavity and before being cabled

